

Oil Field Environmental Incident Summary

Incident: 20160211161017 **Date/Time of Notice:** 02/11/2016 16:10

Responsible Party: Lime Rock Resources

Well Operator: OXY USA INC.

Well Name: MOOSE DROOL 9-16H

Field Name: DIMOND

Well File #: 19363

Date Incident: 2/11/2016

Time Incident: 09:00

Facility ID Number:

County: BURKE

Twp: 160

Rng: 91

Sec: 9

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
3239 hwy 22
Dickinson, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	4	Barrels	2	Barrels	2	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/1/2016

Clean Up Concluded: 2/12/2016

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

The well was shut in to prevent further release, Strata has been dispatched to remediate the affected area.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/11/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on constructed well site according to the report. NDIC retains oversight.